

## ACCESS AUDIT REVIEW

### Brunel Car Park

**Date:** 09/04/2019

**Assessor:** Christian Drewitt and Tasha Everall

#### Car Park

There are 335 spaces in Brunel car park and 5 disabled bays. The disabled bays are on different level to the exit with a lift for access.

The disabled parking bays are within minimum requirements measuring at 2.4m wide with a combined space of 1.3m which leaves plenty of room to exit a vehicle on either side.

There isn't any space at the back of the bay for a rear exit accessible vehicle. There isn't a pedestrian route either, this means that a wheelchair that is leaving a rear exit accessible vehicle will be exiting straight onto the vehicular route.

There are two sets of heavy double push doors to exit the car park which a wheelchair user may find difficult to open alone.

Access to the street is gained via a lift on the left of the double doors. This lift is large enough to fit a wheelchair user and assistant however there is not enough turning space for a wheelchair. The lift has a mirrored back wall so that a wheelchair user can see behind them when reversing out and the control buttons are on the right wall at a suitable height to be reached by a wheelchair user or person of smaller stature.